

# General Environmental Incident Summary

**Incident:** 3338      **Date/Time Notice:** 6/5/2014      1500      **DEM Incident No:**  
**Responsible Party:** RTS Shearing LLC  
**Date Incident:** 6/4/2014      **Time Incident:** 17:20      **Duration:** 90 minutes  
**County:** Logan      **Twp:** 135      **Rng:** 69      **Sec:** 28      **Qtr:** NW NW SW  
**Lat:** 46.47492      **Long:** -99.36890      **Method:** Interpolation from map  
**Location Description:** From Streeter, ND, Depart 52nd St SE / CR-37 toward Dakota St N 0.5 mi,  
Turn right onto ND-30 / Hy 30 SE 9.8 mi, Keep straight onto ND-30 / ND-34  
1.0 mi, Keep straight onto ND-30 2.7 mi, Arrive at near 6455 ND-30, Lehr,  
ND 58460 on the right  
**Submitted By:** Bill Lytle      **Affiliation:**  
**Address:** 2511 17th street SE  
**City:** Jamestown      **State:** ND      **Zip:** 58401

## Received By:

**Contact Person:** Bill Lytle  
2511 17th street SE  
Jamestown, ND 58401

**Distance Nearest Occupied Building:** 0.25 Miles      **Release Contained:** Yes

**Type of Incident:** Vehicle Accident

**Description of Released Contaminant:** Diesel Fuel

**Volume Spilled:** 3.00 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown      **Reported to NRC:** Unknown

## Cause of Incident:

Semi partially rolled on its side and the fuel leaked out the gas cap

## Risk Evaluation:

Contain spill and work quickly to upright the truck to eliminate the potential for surface water contamination.

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

Surface water within 100 ft but the spill was contained immediately and corrective actions prevented any spreading. This spill was small in volume and in rate which aided in its mitigation.

## Action Taken or Planned:

The spill was contained with clay initially. There was roughly 3 ft by 3 ft (9 sq ft or 1/3 yard) of contaminated material produced during the incident. The surrounding area outside the contaminated material was also excavated for a total of 3 yards being removed of which only 1/3 was actually contaminated..

**Wastes Disposal Location:** This contaminated material and the surrounding material was

excavated and hauled to a location in Jamestown, ND where like materials are stockpiled (asphalt) for recycling.

**Agencies Involved:** NDDOT

### **Updates**

---

**Date:** 6/5/2014      **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Volume:**

**Notes:**

Surface water was within 100 feet of contaminant, so followup is necessary.

---

**Date:** 6/6/2014      **Status:** Reviewed - No Action Required

**Author:** O'Gorman, Brian

**Updated Volume:**

**Notes:**

Spoke with the company contact yesterday 6/5/14 and was told that they were working on an NDDOT road project when the release occurred and had equipment on-site to remove and replace the soil as soon as the release occurred.

Spoke with the NDDOT site inspector at 8:10, 6/6/14. The site inspector stated that the release was minimal; they had excavated the impacted area immediately, and the release had been properly remediated.